






LOCATION: NE 137th Ave -- NE 59th St
CITY/STATE: Vancouver, WA

QC JOB #: 10396416
DATE: 12/4/2008



Peak-Hour: 4:05 PM -- 5:05 PM
Peak 15-Min: 4:35 PM -- 4:50 PM



5-Min Count Period Beginning At	NE 137th Ave (Northbound)				NE 137th Ave (Southbound)				NE 59th St (Eastbound)				NE 59th St (Westbound)				Total	Hourly Totals
	Left	Thru	Right	U	Left	Thru	Right	U	Left	Thru	Right	U	Left	Thru	Right	U		
4:00 PM	1	40	0	0	0	30	0	0	1	0	3	0	0	0	0	0	75	
4:05 PM	3	35	0	0	0	40	0	0	1	0	4	0	0	0	0	0	83	
4:10 PM	5	47	0	0	0	50	0	0	1	0	2	0	0	0	0	0	105	
4:15 PM	2	34	0	0	0	30	1	0	3	0	0	0	0	0	0	0	70	
4:20 PM	4	37	0	0	0	47	0	0	1	0	2	0	0	0	0	0	91	
4:25 PM	2	33	0	0	0	34	1	0	0	0	2	0	0	0	0	0	72	
4:30 PM	4	33	0	0	0	46	1	0	1	0	2	0	0	0	0	0	87	
4:35 PM	2	42	0	0	0	57	0	0	2	0	1	0	0	0	0	0	104	
4:40 PM	1	39	0	0	0	46	0	0	1	0	3	0	0	0	0	0	90	
4:45 PM	1	49	0	0	0	38	4	0	0	0	6	0	0	0	0	0	98	
4:50 PM	3	39	0	0	0	44	0	0	1	0	3	0	0	0	0	0	90	
4:55 PM	1	44	0	0	0	34	0	0	0	0	0	0	0	0	0	0	79	1044
5:00 PM	1	47	0	0	0	54	0	0	0	0	3	0	0	0	0	0	105	1074
5:05 PM	0	37	0	0	0	39	0	0	2	0	0	0	0	0	0	0	78	1069
5:10 PM	3	39	0	0	0	33	1	0	0	0	2	0	0	0	0	0	78	1042
5:15 PM	2	44	0	0	0	43	0	0	2	0	3	0	0	0	0	0	94	1066
5:20 PM	4	43	0	0	0	40	2	0	0	0	2	0	0	0	0	0	91	1066
5:25 PM	1	32	0	0	0	39	0	0	0	0	4	0	0	0	0	0	76	1070
5:30 PM	1	33	0	0	0	34	0	0	0	0	3	0	0	0	0	0	71	1054
5:35 PM	3	32	0	0	0	34	2	0	1	0	3	0	0	0	0	0	75	1025
5:40 PM	1	32	0	0	0	32	0	0	1	0	2	0	0	0	0	0	68	1003
5:45 PM	1	41	0	0	0	38	1	0	0	0	3	0	0	0	0	0	84	989
5:50 PM	0	20	0	0	0	35	1	0	0	0	4	0	0	0	0	0	60	959
5:55 PM	1	22	0	0	0	25	0	0	0	0	0	0	0	0	0	0	48	928
Peak 15-Min Flowrates	Northbound				Southbound				Eastbound				Westbound				Total	
All Vehicles	16	520	0	0	0	564	16	0	12	0	40	0	0	0	0	0	1168	
Heavy Trucks	4	12	0	0	0	16	0	0	0	0	0	0	0	0	0	0	32	
Pedestrians		0				0				0				0			0	
Bicycles																		
Railroad																		
Stopped Buses																		

Comments: